

### Affects:

- Conettix DX4020 Ethernet Network Interface Modules (NIMs) with v2.21 firmware or earlier
- BIS 2.x Security Engine
- BIS 2.x Admin9000 Module
- ReadykeyPRO® Software
- Other automation systems connected to control panels using DX4020 NIMs

### 1.0 Issue

Connecting automation system software to control panels using DX4020 NIMs with v2.21 or earlier firmware might result in:

- Lost alarm events
- Duplicate alarm events
- Invalid reporting of system status

In the case of BIS, check the OPC9000 log files (located in **MgtS\S3kLogging**) for the text string **Unexpected User Defined Status Response**. If you find this text string, your automation system is affected by this issue.

### 2.0 Resolution

Upgrade the DX4020 firmware to v2.22.

Call Bosch Security Systems, Inc. Customer Service at (800) 289-0096, and request the DX4020 firmware upgrade kit (P/N: R21-DX40XX-ROM).

### Trademarks

ReadykeyPRO® is a trademark of Bosch Security Systems, Inc. in the United States.

