

TECHNICAL BULLETIN

Intrusion

RADION Repeater

Incorrect AC Notifications

September 24, 2014

Issue Severity:

☐

High: Act immediately

☒

Medium: Bosch Security Systems strongly recommends you take the action(s) described below.

☐

Low: Advisory

Products Affected:

- RADION Repeater RFRP

1.0 Issue

While connected to AC power and functioning normally, a RADION repeater, RFRP, might incorrectly send “AC Fail” and “AC Restore” messages to the control panel. **Important!** The repeater is otherwise functioning correctly. However, the control panel event log might store multiple AC Fail and AC Restore events.

Notice! This issue does not occur with the RFRP-A or RFRP-CHI repeater.

2.0 Resolution

Bosch Security Systems, Inc. is correcting the problem. New product will be available October 6, 2014. If your equipment experiences this condition in the field, have the repeater replaced using Bosch's advanced warranty replacement process.



BOSCH

