

### **Affects: Newer POPIT Label Sheets Included with each D8125 Popex Zone Expansion Module**

#### **Issue**

Six of the individual POPIT labels on the 9000 Series Bank One (9 to 128) and Bank Two (129 to 248) *Label Sheets* (P/N: 79-07675-000-A) have incorrect switch settings affecting the following points:

- 012
- 018
- 114
- 132
- 138
- 234

#### **Resolution**

These six labels have Switch 6 set to **On**; the correct position for this switch is **Off**. Please cross out the number “6” on the corresponding labels to ensure accurate switch setting during installation.

These incorrect labels can be identified by the green tinted paper backing and the date “9/96.” Older versions are printed on regular label stock.

Newer corrected labels have the date “10/99” and part number 79-07675-000-B.

Please contact Bosch Security Systems Technical Support at (888) 886-6189 should you require label replacements.



